

COMMISSIONER'S MONTHLY REPORT

Commissioner

Date Sept 3 1964

Report for Month of August 1964

Day of the Month

Source and Point of Measurement	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Second feet of water															
I. Boardman Springs															
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)													1.22		
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. water)													0.70		
#3. Church ditch near to heading													1.65		
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the FR right-of-way)													2.28		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													1.65		
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the FR right-of-way)													2.09		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													2.66		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													2.23		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													1.04		
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake													0.29		
II. Thomas Spring													3.01		
#5. Above the Olsen house below the tracks													2.74		
III. Drain													0.75		
#6. Drain Channel near Railroad Shop and Burningham properties													0.70		
IV. #8. Levie Ditch - Water to Church Farm, etc.													0.00		
IV. #8. Levie Ditch - Water to Church Farm, etc.													4.97		
V. #9. Pump Water at Church Welfare Farm													0.00		
V. #9. Pump Water at Church Welfare Farm													4.00		

Submitted by

Lewis Allen
Lewis Allen

For key to location numbers see drawing P-5107

* Note: The Church welfare farm at this reading
was taking a total of 8.97 sec. feet of water.